

Sourcetec Industries

Application Case Studies

WASH BAY CURTAINS



Project: Dealership with Car Wash Bay

Problem: Chemicals and water overspray leak to surrounding area.

Solution: 2 - Sourcetec Wash Bay Curtains with clear middle section for safety and light. Curtains are hung from an overhead track so they can be opened and closed when needed.



Results: Curtains are pulled out to separate work areas. Chemicals and overspray are safely contained in the wash bay area.

Additional Note: Sourcetec Wash Bay Curtains come in many different colors and combinations. Lengths can be custom sized to your shop or Facility.



Ontario, Canada, L5S 1E7
Tel: (905) 678-9333 Fax: (905) 678-7133
Ohio, USA 43528
Toll Free: 1-800-784-2383
www.sourcetecindustries.com